

2010 Hitachi ZX330-3 Hydraulic Excavator

Basic information			
Inspection date	2022/06/16	Model	ZX330-3
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	HCM1V700H00058489	Working hours	3704 hours
Year of manufacture	2010	Engine No.	
Price			
Country	Malaysia	Yard Location	Kota Kinabaru
Dealer	Hitachi Construction Machinery Asia & Pacific	Dealer	
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	ROPS	Front Attachment	Standard, Backhoe
Type of Shoe	Grouser	Other	Air Conditioner
Premium Used	Premium Used		
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Good Condition	D Frame	Good Condition
Track Frame	Good Condition	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucket	Good		
Undercarriage / Chassis / Tires			
Wear: Track Link Stretching (Right)	Moderate	Wear: Track Link Stretching (Left)	Moderate
Wear: Track Link Tread (Right)	Moderate / within Service Limit	Wear: Track Link Tread (Left)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber Shoe	Slight	Bent / Broken / Missing: Track Shoe	No
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None

Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Arm Cylinder (Left)	None	Oil Leak: Bucket Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Left)	None	Oil Leak: Offset Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Center Joint	None	Oil Leak: Swing Device	None
Oil Leak: Pump Device	None		

Overall Rating

Appearance Evaluation	Excellent	Rust / Corrosion	No
-----------------------	-----------	------------------	----

Overall Rating Like Brand-New (Including Demo Machine)

Special Notes

- * new undercarriage rollers;
- * Bucket Cylinder, Boom Cylinders, Arm Cylinder overhauled with new genuine parts;
- * Engine overhauled with genuine parts, new fan, trouble charger, etc.
- * Full set new wiring harness;
- * main control valve overhauled;
- * Genuine Hitachi Reman components: Hydraulic main pump, travel device, center joint, swing device
- * Replaced





