CAT D5H Bulldozer/Tractor Shovel

Basic information			
Inspection date	20211014	Model	D5H
Product category	Bulldozer/Tractor Shovel	Manufacturer	CAT
Serial No.	4KD05564	Working hours	7227 hours
Year of manufacture		Engine No.	
Price			
Country	Japan	Yard Location	Sakura
Dealer	Hitachi Construction Machinery	Dealer	
	Japan Co., Ltd.		
Detail Information			
Job Status	General Contractor / Civil Engineering	Cabin / Canopy	Cabin
Cabin Type	Standard	Power Transmission System	Torque Converter
Type of Shoe	Triangle	Width of Track Shoe	860
Front Attachment	PAT	Other	Air Conditioner
Appearance			
	Missing	Side Covers	Rusted / Corroded
Engine Cover Under Covers	Missing Rusted / Corroded	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Lift (Push) Arm	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Latch Malfunction
	Rusieu / Corrodeu	D001	Later Manufetion
Interior			
Cabin Interior	Torn	Seat	Dirty
Console	Faded	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Poor Pedal Movement	Steering	Normal
Front Attachment	Slow		
Front & Pins			
Wear: Front Pins	Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Lim
Wear: Tooth / Cutting	Widderate / Within Service Limit	Weal / Deloffiation. Blade	Wear. Moderate / Within Service Lim
Edges	Slight	Wear: Bucket Side Plate	Slight
Wear: Bucket Lip	Slight	Wear: Bucket Bottom Plate	Slight
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link Extension (Right)	Excessive
Wear: Track Link Extension (Left)	Excessive	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Excessive / Required to replace
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Excessive / Required to replace
Wear: Lower Rollers	Excessive / Required to replace	Oil Leak: Rollers	1 - 4 Pieces
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Rear Idler (Right)	Moderate / within Service Limit
Wear: Rear Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit		

Oil / Water / Air Leakage				
Oil Leak: Front Pipes	Excessive / Required to Repair	Oil Leak: Lift Cylinder (Right)	None	
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Tilt Cylinder (Right)	Moderate Oozing	
Oil Leak: Tilt Cylinder (Left)	Moderate Oozing	Oil Leak: Angle Cylinder	None	
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None	
Leak: Radiator	None	Leak: Cooling Pipes	Slight Film	
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	Slight Film	
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	None	
Oil Leak: Pump Device	None	Oil Leak: Transmission / Torcon	None	
Overall Rating				
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit	
Overall Rating	Usable			
	アングルシリンダ配管腐食・ホース破損油漏れ、各操作レバー重い、三角シュー板厚薄く摩耗大、			
	右走行フレーム〜センターフレームジョイント軸受にじみ漏れ、エンジン左サイドカバー欠品、			
Special Notes	ブレード左右チルトシリンダ油にじみもれ、キャブ内ベッド腐食大			
	キャブドアハンドル不良、ホーン不鳴り、燃料メータ作動不良			
	在庫場所が極狭の為、試運転走行は低速のみ			





















































