2020 Hitachi ZX360K-5A Hydraulic Excavator

Basic information			
Inspection date	2022/06/21	Model	ZX360K-5A
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	DDKB3A600661	Working hours	1239 hours
Year of manufacture	2020	Engine No.	
Price	CNY 1,050,000		
Country	China	Yard Location	Inner Mongolia Autonomous Region
Dealer	内蒙日强	Dealer	
Detail Information			
Job Status	????		
Appearance			
Counter Weight	Scratched	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Cour	Cood Containon
Operation	Normal	Exhaust Coa Color	Normal
Engine		Exhaust Gas Color	
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil / Water / / til Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
······ ·	None None	_	None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder		(Right) Oil Leak: Arm Cylinder	
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder	None	(Right) Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right)	None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler	None None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator	None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve	None None None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve Oil Leak: Swing Device	None None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve Oil Leak: Center Joint	None None None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve Oil Leak: Swing Device Overall Rating	None None None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve Oil Leak: Center Joint Oil Leak: Pump Device	None None None None None
Oil Leak: Front Pipes Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve Oil Leak: Swing Device	None None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve Oil Leak: Center Joint	None None None None











