

# 2018 Hitachi EH1100-3 Dump Truck

Basic information			
Inspection date	2018/10/05	Model	EH1100-3
Product category	Dump Truck	Manufacturer	Hitachi
Serial No.	HTMQBC80N001100002	Working hours	
Year of manufacture	2018	Engine No.	
Price			
Country	Canada	Yard Location	Canada
Dealer	Hitachi Construction Truck Manufacturing Ltd.	Dealer	
Detail Information			
Mileage (km)	0	Job Status	Quarry, Mining
Size of Tire	R35	Loading capacity	65 t
Vehicle Inspection	Documents available	Other	Air Conditioner, Cooler, Heater
Documents	Available	Recommended	
Appearance			
Main Frame	Good Condition	Cover	Good Condition
Cabin / Driving seat	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good Condition
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Scratches: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Front-Left Wheel)	Slight	Scratches: Tire (Rear-Left Wheel)	Slight
Wear: Tire (Front-Right wheel)	No	Wear: Tire (Front-Left Wheel)	No
Wear: Tire (Rear-Right Wheel)	No	Wear: Tire (Rear-Left Wheel)	No
Oil Leak: Travel Device	No	Oil Leak: Axle	No
Oil Leak: Differential Gear Case	No		
Oil / Water / Air Leakage			
Engine shaft seal	No	Tappet cover	No
Oil pan	No	Head gasket	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Compressor	Normal	Oil Leak: Control Valve	No
Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No	Transmission / Torque Converter	No
Dump cylinder (Right)	No	Dump cylinder (Left)	No
Ram cylinder	No	Oil Leak: Engine	No
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Gearshift	Normal
Break	Normal	Side Break	Normal
Dumping	Normal	Other working device	Normal

