

# 2018 Kawasaki 95Z7B Wheel Loader

Basic information			
Inspection date	2021/07/07	Model	95Z7B
Product category	Wheel Loader	Manufacturer	Kawasaki
Serial No.	97J2-5028	Working hours	3888 hours
Year of manufacture	2018	Engine No.	
Price			
Country	United States of America	Yard Location	Louisiana
Dealer	Hitachi Construction Machinery Loaders America Inc.	Dealer	
Detail Information			
Job Status	Rental	Type of Tire	Normal
Appearance			
Main Frame	Good Condition	Front Frame	Good Condition
Counter Weight	Good Condition	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	HST Motor	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Normal	Swing	Normal
Outrigger	Normal		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Slight	Wear: Bucket Pins & Bushings	Slight
Wear: Center Pins	Slight	Wear: Bucket Side Plate	Slight
Wear: Bucket Lip	Slight	Wear: Bucket Bottom Plate	Slight
Wear: Tooth / Cutting Edges	Slight		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Slight
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Slight	Wear: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Slight
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	Moderate Oozing
Oil Leak: Lift Cylinder (Left)	Moderate Oozing	Oil Leak: Bucket Cylinder	Slight Film
Oil Leak: Steering Cylinder	None	Oil Leak: Tilt Cylinder	None

Oil Leak: Angle Cylinder (Right)	None	Oil Leak: Angle Cylinder (Left)	None
Oil Leak: Swing Cylinder	None	Oil Leak: Outrigger Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Compressor	Normal
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Oil Leak: Transmission / Torcon	None		

Overall Rating			
Appearance Evaluation	Excellent	Rust / Corrosion	No
Overall Rating	Good		
Special Notes	This machine has been on dealer owned rent and in good condition with normal wear and tear . No ride control switch.		

















