## 2007 Hitachi ZX240-3 Hydraulic Excavator

Basic information			
Inspection date	2020/03/25	Model	ZX240-3
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	1V1A021419	Working hours	8 hours
Year of manufacture	2007	Engine No.	
Price	CNY 750,000		
Country	China	Yard Location	Liaoning Province
Dealer	辽宁恒力	Dealer	7
Detail Information			
Recommended			
Appearance			
Counter Weight	Good Condition	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Jour	Cood Condition
	2004 Containon		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link Tread	Slight
	110	(Right)	Oligiti
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins &	Slight	Broken / Crack: Rubber	No
Bushings (Left)		Shoe (Right)	
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
······ <del>·</del>		Oil Leak: Boom Cylinder	<b>.</b>
Oil Leak: Front Pipes	None	-	None
Oil Leak: Boom Cylinder	None	(Right) Oil Leak: Arm Cylinder	None
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder		(Right)	
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right)	None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler	None None
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator	None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve	None None None
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve	None None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve Oil Leak: Center Joint	None None None
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve Oil Leak: Swing Device	None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve	None None None
Oil Leak: Boom Cylinder (Left) Oil Leak: Bucket Cylinder (Right) Leak: Radiator Oil Leak: Pilot Valve	None None None None	(Right) Oil Leak: Arm Cylinder (Right) Oil Leak: Oil Cooler Oil Leak: Control Valve Oil Leak: Center Joint	None None None











































