

2021 Hitachi ZX300-5A Hydraulic Excavator

Basic information			
Inspection date	2022/06/21	Model	ZX300-5A
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	HHEDDWB0C00100843	Working hours	1365 hours
Year of manufacture	2021	Engine No.	
Price	CNY 890,000		
Country	China	Yard Location	Inner Mongolia Autonomous Region
Dealer	内蒙日强	Dealer	
Detail Information			
Job Status	????		
Appearance			
Counter Weight	Scratched	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Excellent	Rust / Corrosion	No
Overall Rating	Like Brand-New (Including Demo Machine)		



