

2017 Hitachi ZX360H-5A Hydraulic Excavator

Basic information			
Inspection date	2023/02/01	Model	ZX360H-5A
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	DDKB2J300525	Working hours	4937 hours
Year of manufacture	2017	Engine No.	6HK1-905557
Price	CNY 620,000		
Country	China	Yard Location	Shanxi
Dealer	山西伟力	Dealer	
Appearance			
Counter Weight	Good Condition	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Good	Rust / Corrosion	Slight
Overall Rating	Good		
Special Notes	机滤渗油，液压泵进油管渗油。		







