



# 2023 B45E Dump Truck

Basic information			
Inspection date	2024/12/24	Model	B45E
Product category	Dump Truck	Manufacturer	Others
Serial No.	AEBA845EV03408859	Working hours	3025 hours
Year of manufacture	2023	Engine No.	
Price			
Country	Indonesia	Yard Location	Samarinda
Dealer	PT Hexindo Adiperkasa Tbk	Dealer	
Detail Information			
Job Status	Mining	Vehicle Inspection	Documents available
Other	EPA, Air Conditioner, Cooler, Heater	License Number Plate	Exist
Bottom plate	Normal	Recommended	
Premium Used	Premium Used		
Appearance			
Main Frame	Good Condition	Cover	Good Condition
Cabin / Driving seat	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good Condition
Oil / Water / Air Leakage			
Engine shaft seal	No	Tappet cover	No
Oil pan	No	Head gasket	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Compressor	Normal	Oil Leak: Control Valve	No
Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No	Transmission / Torque Converter	No
Dump cylinder (Right)	No	Dump cylinder (Left)	No
Ram cylinder	No	Oil Leak: Engine	No







OPPO F11 - ©8859  
2024/11/24 08:43



OPPO F11 - ©8859  
2024/11/24 08:44



OPPO F11 - ©8859  
2024/11/24 08:45



OPPO F11 - ©8859  
2024/11/24 08:45



OPPO F11 - ©8859  
2024/11/24 08:46



OPPO F11 - ©8859  
2024/11/24 08:46



OPPO F11 - ©8859  
2024/11/24 08:46



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859  
2024/11/24 08:47



OPPO F11 - ©8859 radio not funct  
2024/11/24 08:50



OPPO F11 - ©8859  
2024/11/24 08:51







