

2023 B45E Dump Truck

Thông tin cơ bản			
Ngày kiểm tra	2025/01/02	Mô hình	B45E
Danh mục sản phẩm	Dump Truck	nhà chế tạo	Others
Không có nối tiếp.	AEBA845EJ03408938	Giờ làm việc	3007 giờ
Năm sản xuất	2023	Động cơ số	
Giá bán			
Quốc gia	Indonesia	Vị trí sân	Samarinda
Người buôn bán	PT Hexindo Adiperkasa Tbk	Người buôn bán	
Detail Information			
Job Status	Mining	Power Transmission System	Torque Converter
Vehicle Inspection	Documents available	Other	EPA, Air Conditioner, Cooler, Heater
Documents	Available	License Number Plate	Exist
Bottom plate	Normal	Recommended	
Premium Used	Premium Used		
Appearance			
Main Frame	Good Condition	Cover	Good Condition
Cabin / Driving seat	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good Condition
Oil / Water / Air Leakage			
Engine shaft seal	No	Tappet cover	No
Oil pan	No	Head gasket	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Compressor	Normal	Oil Leak: Control Valve	No
Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No	Transmission / Torque Converter	No
Dump cylinder (Right)	No	Dump cylinder (Left)	No
Ram cylinder	No	Oil Leak: Engine	No
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Gearshift	Normal
Break	Normal	Side Break	Normal
Dumping	Normal	Crane	Normal
Other working device	Normal		
Vessel			
Vessel	Normal		
Overall Rating			
Appearance Evaluation	Excellent	Rust / Corrosion	No













