2011 Hitachi EH1100-3 Dump Truck

Thông tin cơ bản			
Ngày kiểm tra	2025/02/13	Mô hình	EH1100-3
Danh mục sản phẩm	Dump Truck	nhà chế tạo	Hitachi
Không có nối tiếp.	HTM8R4ABN00001187	Giờ làm việc	17088 giờ (Estimated)
Năm sản xuất	2011	Động cơ số	
Giá bán			
Quốc gia	MIDDLE EAST	Vị trí sân	Hitachi Construction Machinery Middle East (Jebel Ali Free Zone)
Người buôn bán	HMEC	Người buôn bán	
Detail Information			
Size of Tire	24.00R35	Other	Air Conditioner
Documents	Not Existing	License Number Plate	No
Appearance			
Cabin / Driving seat	Good Condition	Door	Good Condition
Interior			
Seat	Good Condition	Air Conditioner	Good Condition
		rui Condidition	cood contains
Undercarriage / Chassis / Ti			
Oil Leak: Travel Device	No	Oil Leak: Axle	No
Oil Leak: Differential Gear Cas	e No		
Oil / Water / Air Leakage			
Engine shaft seal	No	Tappet cover	No
Oil pan	No	Head gasket	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Compressor	Normal	Oil Leak: Control Valve	No
Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No	Transmission / Torque Converter	No
Dump cylinder (Right)	No	Dump cylinder (Left)	No
Ram cylinder	No	Oil Leak: Engine	No
Operation			
Exhaust Gas Color	Normal	Traveling	Normal
Steering	Normal	Dumping	Normal
Vessel			
Vessel	Normal		
Overall Rating	AC Boor View Comers Air Bid	o Coot Auto Lubo Foot Find Fill 04 000	DE Tiron Eiro Cuppr
Special Notes	AC, Rear View Camera, Air Ride Seat, Auto Lube, Fast Fuel Fill, 24.00R35 Tires, Fire Suppr ession System, Engine model: MTU 12V2000 Transmission model: Allison H6610A		











































