

# Hitachi ZW310-A Wheel Loader

Basic information			
Inspection date	20211118	Model	ZW310-A
Product category	Wheel Loader	Manufacturer	Hitachi
Serial No.	S58-06371	Working hours	32206 hours
Year of manufacture		Engine No.	
Price			
Country	Japan	Yard Location	Sakura
Dealer	Hitachi Construction Machinery Japan Co., Ltd.	Dealer	
Detail Information			
Job Status		Mileage (km)	157183
Type of Tire	Normal	License Plate	No
Documents	Not Existing	Cabin / Canopy	Cabin
Cabin Type	ROPS	Power Transmission System	Torque Converter
Drive System	All Wheel Drive	Size of Tire	26.5-25-24PR
Bucket Attachment	Digging BK	Other	Air Conditioner
Appearance			
Main Frame	Rusted / Corroded	Front Frame	Rusted / Corroded
Counter Weight	Scratched	Cabin	Glass: Broken
Door	Latch Malfunction		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Malfunction	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Front Attachment	Normal
Pump Device	Normal	Steering	Normal
Break	Malfunction	Side Break	Normal
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Bucket Pins & Bushings	Moderate / within Service Limit
Wear: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Moderate / within Service Limit
Wear: Bucket Lip	Moderate / within Service Limit	Wear: Bucket Bottom Plate	Excessive / Required
Wear: Tooth / Cutting Edges	Moderate / within Service Limit		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	Moderate Oozing
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	Slight Film	Oil Leak: Bucket Cylinder	None

Oil Leak: Steering Cylinder	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Compressor	Normal	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Pump Device	Moderate Oozing	Oil Leak: Transmission / Torcon	Moderate Oozing

Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Ser
Overall Rating	Usable		

Special Notes	<ul style="list-style-type: none"> <li>・アワーメーターより「使用可能」判断。</li> <li>・ブレーキペダル及びインチャージペダル、作動・踏込むと錆?の影響で元に戻って来ない（一回一回手で戻さないと戻らない）</li> <li>・走行前進時、3速までしかいれていないのに、すぐに4速表示になる（モニター部の不良?、トランスミッション?）</li> <li>・ラジエター前カバーロック不良、エンジンカバー変形。</li> </ul>
---------------	---









