

# CAT 303C CR Mini Excavator

| Basic information                       |   |  |                                 |
|---|---|--|---------------------------------|
| Inspection date                         | 20220310  | Model                                    | 303C CR                         |
| Product category                        | Mini Excavator                                    | Manufacturer                             | CAT                             |
| Serial No.                              | AZS03601  | Working hours                            | 16 hours                        |
| Year of manufacture                     |   | Engine No.                               |                                 |
| Price                                   |   |  |                                 |
| Country                                 | Japan   | Yard Location                            | Sakura                          |
| Dealer                                  | Hitachi Construction Machinery<br>Japan Co., Ltd. | Dealer                                   |                                 |
| Detail Information                      |   |  |                                 |
| Job Status                              | Civil Engineering                                 | Cabin / Canopy                           | Canopy                          |
| Front Attachment                        | Standard  | Type of Shoe                             | Grouser with Pad                |
| Width of Track Shoe                     | 300   | Bucket Attachment                        | Standard                        |
| Other                                   | Piping, Multi Lever                               |  |                                 |
| Appearance                              |   |  |                                 |
| Engine Cover                            | Good Condition                                    | Side Covers                              | Missing                         |
| Under Covers                            | Deformed / Dent                                   | Counter Weight                           | Scratched                       |
| Main Frame                              | Good Condition                                    | Track Frame                              | Deformed / Dent                 |
| Cabin                                   | Deformed / Dent                                   |  |                                 |
| Interior                                |   |  |                                 |
| Seat                                    | Torn  | Console                                  | Good Condition                  |
| Operation                               |   |  |                                 |
| Engine                                  | Normal  | Exhaust Gas Color                        | Normal                          |
| Swing                                   | Normal  | Wear: Swing Bearing                      | Moderate / within Service Limit |
| Traveling                               | Normal  | Front Attachment                         | Normal                          |
| Front & Pins                            |   |  |                                 |
| Boom                                    | Normal  | Arm                                      | Reinforcement                   |
| Wear: Boom Foot Pin                     | Heavy   | Wear: Boom / Arm Joint Pin               | Moderate / within Service Limit |
| Wear: Arm Tip Pin                       | Heavy   | Wear: Other Pins                         | Heavy                           |
| Wear / Deformation: Bucket              | Deformation: Moderate                             | Wear / Deformation: Blade                | Deformation: Moderate           |
| Undercarriage / Chassis / Tires         |   |  |                                 |
| Seize: Track Links                      | No  | Wear: Track Link Stretching (Right)      | Moderate                        |
| Wear: Track Link Stretching (Left)      | Moderate  | Wear: Track Link Tread (Right)           | Moderate / within Service Limit |
| Wear: Track Link Tread (Left)           | Moderate / within Service Limit                   | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit |
| Wear: Track Link Pins & Bushings (Left) | Moderate / within Service Limit                   | Wear: Track Shoe / Rubber Shoe           | Slight                          |
| Bent / Broken / Missing: Track Shoe     | No  | Wear: Rubber Pad                         | Slight                          |
| Broken / Missing: Rubber Pad            | No  | Missing: Rubber Pad                      | No                              |
| Wear: Upper Rollers                     | Moderate / within Service Limit                   | Wear: Lower Rollers                      | Moderate / within Service Limit |
| Oil Leak: Rollers                       | 1 - 4 Pieces                                      | Broken / Missing: Rollers                | 1 - 4 Pieces                    |
| Wear: Front Idler (Right)               | Moderate / within Service Limit                   | Wear: Front Idler (Left)                 | Moderate / within Service Limit |
| Wear: Sprocket (Right)                  | Moderate / within Service Limit                   | Wear: Sprocket (Left)                    | Moderate / within Service Limit |
| Oil Leak: Travel Device                 | None  | Oil Leak: Travel Pipes                   | None                            |
| Oil / Water / Air Leakage               |   |  |                                 |
| Oil Leak: Front Pipes                   | None  | Oil Leak: Boom Cylinder                  | None                            |

|                          |      |                           |                                |
|--------------------------|------|---------------------------|--------------------------------|
| Oil Leak: Arm Cylinder   | None | Oil Leak: Bucket Cylinder | None                           |
| Oil Leak: Swing Cylinder | None | Oil Leak: Blade Cylinder  | None                           |
| Oil Leak: Engine         | None | Oil Leak: Oil Cooler      | Excessive / Required to Repair |
| Leak: Radiator           | None | Leak: Cooling Pipes       | None                           |
| Oil Leak: Fuel System    | None | Oil Leak: Upper Structure | None                           |
| Oil Leak: Under Carriage | None | Oil Leak: Pilot Pipes     | None                           |
| Oil Leak: Pilot Valve    | None | Oil Leak: Pump Device     | None                           |

|                       |                                 |                  |                                 |
|-----------------------|---------------------------------|------------------|---------------------------------|
| Overall Rating        |                                 |                  |                                 |
| Appearance Evaluation | Poor                            | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating        | Usable                          |                  |                                 |
| Special Notes         | T対象                             |                  |                                 |
|                       | 本体右側損傷                          |                  |                                 |
|                       | オイルクーラー外し、オイルクーラーレスのためオーバーヒートあり |                  |                                 |
|                       | 1400hr時メーター交換あり                 |                  |                                 |









