## 2007 Hitachi ZX240-3 Hydraulic Excavator

Pacia information			
Basic information Inspection date	2020/03/25	Model	ZX240-3
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	1V1A021419	Working hours	8 hours
Year of manufacture	2007	Engine No.	o nours
Price	CNY 750,000	Linginie INO.	
Country	China	Yard Location	Liaoning Province
Dealer	辽宁恒力	Dealer	Lidolining i Tovilloe
Detail Information	-1-3		
Recommended			
Appearance			
Counter Weight	Good Condition	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis /	/ Tilles	\\\/T.	
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread	Slight	Wear: Track Link Pins &	Slight
(Left)	3	Bushings (Right)	
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Boom Cylinder		(Right) Oil Leak: Arm Cylinder	
(Left)	None	(Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Overall Rating Appearance Evaluation	Excellent	Rust / Corrosion	No











































