

2013 Hitachi ZX240-3 Hydraulic Excavator

| Basic information | | | |
|---|---|--|-------------------|
| Inspection date | 2020/04/30 | Model | ZX240-3 |
| Product category | Hydraulic Excavator | Manufacturer | Hitachi |
| Serial No. | AWUJ102103 | Working hours | 7 hours |
| Year of manufacture | 2013 | Engine No. | |
| Price | CNY 750,000 | | |
| Country | China | Yard Location | Liaoning Province |
| Dealer | 辽宁恒力 | Dealer | |
| Detail Information | | | |
| Recommended | | | |
| Appearance | | | |
| Counter Weight | Good Condition | Main Frame | Good Condition |
| D Frame | Good Condition | Track Frame | Good Condition |
| Cabin | Good Condition | Door | Good Condition |
| Interior | | | |
| Cabin Interior | Good Condition | Seat | Good Condition |
| Console | Good Condition | | |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Undercarriage / Chassis / Tires | | | |
| Seize: Track Links | No | Wear: Track Link Tread (Right) | Slight |
| Wear: Track Link Tread (Left) | Slight | Wear: Track Link Pins & Bushings (Right) | Slight |
| Wear: Track Link Pins & Bushings (Left) | Slight | Broken / Crack: Rubber Shoe (Right) | No |
| Broken / Crack: Rubber Shoe (Left) | No | Wear: Front Idler (Right) | Slight |
| Wear: Front Idler (Left) | Slight | Wear: Sprocket (Right) | Slight |
| Wear: Sprocket (Left) | Slight | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |
| Oil Leak: Boom Cylinder (Left) | None | Oil Leak: Arm Cylinder (Right) | None |
| Oil Leak: Bucket Cylinder (Right) | None | Oil Leak: Oil Cooler | None |
| Leak: Radiator | None | Oil Leak: Control Valve | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Center Joint | None |
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Excellent | Rust / Corrosion | No |
| Overall Rating | Like Brand-New (Including Demo Machine) | | |



