2007 Hitachi ZX240-3 Hydraulic Excavator

Doois information			
Basic information	2024/02/24	Model	7V240.2
Inspection date	2021/03/31	Model Manufacturer	ZX240-3
Product category Serial No.	Hydraulic Excavator AWUK101113		Hitachi 20 hours
Serial No. Year of manufacture	2007	Working hours	ZUTIOUIS
		Engine No.	
Price	CNY 750,000 China	Yard Location	Ligonina Province
Country Dealer	辽宁恒力	Dealer	Liaoning Province
	以 了但刀	Dealer	
Detail Information			
Recommended			
Appearance			
Counter Weight	Good Condition	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal	. Tom / Madrimont	. tomai
Front & Pins			
	Normal	۸rm	Normal
3oom	Normal	Arm	Normal
Undercarriage / Chassis	: / Tires		
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage)		
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Excellent	Rust / Corrosion	No
Overall Rating	Like Brand-New (Including Demo Machine)		







