

2013 Hitachi ZX360H-5G Hydraulic Excavator

Basic information			
Inspection date	2022/07/22	Model	ZX360H-5G
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	DDEB2H100060	Working hours	5975 hours
Year of manufacture	2013	Engine No.	
Price	CNY 400,000		
Country	China	Yard Location	Shanxi
Dealer	山西伟力	Dealer	
Appearance			
Counter Weight	Scratched	Main Frame	Good Condition
D Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Torn	Seat	Dirty
Console	Broken		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		
Special Notes	正常使用		



