## 2017 Hitachi ZX360H-5A Hydraulic Excavator

Basic information			
nspection date	2023/02/01	Model	ZX360H-5A
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Serial No.	DDKB2J300525	Working hours	4937 hours
Year of manufacture	2017	Engine No.	6HK1-905557
Price	CNY 620,000		
Country	China	Yard Location	Shanxi
Dealer	山西伟力	Dealer	
Appearance			
Counter Weight	Good Condition	Main Frame	Good Condition
O Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Cour	Cook Condition
<u> </u>	2304 CONMINON		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Wear: Front Idler (Right)	Slight
Near: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Vear: Sprocket (Left)	Slight	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder Right)	None	Oil Leak: Oil Cooler	None
₋eak: Radiator	None	Oil Leak: Control Valve	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Good	Rust / Corrosion	Slight
Overall Rating	Good		































































